




TEST PROCEDURE:

To simulate welding slag, a metal nut was heated to various temperatures to observe the reaction on sample swatches of M+A Matting's Hog Heaven, and Superior Manufacturing's Duratrax, and Ergo Mat. Below are the results which were conducted by an independent testing lab, Professional Testing Laboratory, Inc.

TEMPERATURE TESTED	Hog Heaven® by M+A Matting Test #135292	Duratrax by Superior Manufacturing Test #135291	Ergo Mat by Superior Manufacturing Test #146178
600° F	 <p>Sample #5 Sample barely smoked and area hot nut was placed had very slight effect.</p>	 <p>Sample #5 Sample lightly smoked and slightly melted at the spot of hot metal nut. Indicated by slight marred appearance.</p>	 <p>Sample #5 Sample lightly smoked and slightly melted at the spot of hot metal nut. Indicated by slight marred appearance.</p>
900° F	 <p>Sample #4 Sample smoked but did not ignite surface. Indicated by slightly scorched area.</p>	 <p>Sample #4 Sample lightly smoked and slightly melted at the spot of hot metal nut. Indicated by noticeable melted surface.</p>	 <p>Sample #4 Sample lightly smoked and slightly melted at the spot of hot metal nut. Indicated by noticeable melted surface.</p>
1200° F	 <p>Sample #3 Sample had small flame which quickly extinguished. Had slight charring.</p>	 <p>Sample #3 Sample ignited at the spot of the hot metal nut and burned slightly larger hole into material. Indicated by the charred and sunken area.</p>	 <p>Sample #3 Sample smoldered upon contact with hot metal nut.</p>
1500° F	 <p>Sample #2 Sample ignited at spot of hot metal nut and burned area same size as the nut.</p>	 <p>Sample #2 Sample ignited at the spot of hot metal nut, burned to edge of material. Indicated by large charred area.</p>	 <p>Sample #2 Sample ignited upon contact with hot metal nut.</p>
1800° F	 <p>Sample #1 Sample ignited at spot of hot metal nut and burned area slightly larger than nut. Area bulged and charred.</p>	 <p>Sample #1 Sample ignited at the spot of hot metal nut, burned to edge of material. Indicated by large charred area.</p>	 <p>Sample #1 Sample ignited upon contact with hot metal nut.</p>

Hog Heaven
Caution Yellow Striped Border

www.mamating.com